

Work Order ID 59841

Monday, June 14, 2010 8:55:33 AM

Page 1

Item ID: D600-572-015

Accept

Revision ID:

Item Name: Bearpaw

Start Date: 6/7/2010 Start Qty: 1.00

Required Date: 6/14/2010 Req'd Qty: 1.00

Reference: Return 2010 RA110046

Cust Item ID:

Customer:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: [Signature] Date: 10-06-14 SPC (Y/N): _____ Date: _____

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D600-572	Rev A

100 QC5- Inspect part completeness to step on W/O 0.00



QC

Quality Control

Memo 0.00

Original B42790 @ CHG002. Kit was not opened & complete.

110 Identify as per dwg & Stock Location: _____ 0.00



Packaging

Packaging

Memo 0.00

New paperwork & labels required to return to stock with the new batch #, @ CHG002.

120 QC21- Final Inspection - Work Order Release 0.00



QC

Quality Control

Memo 0.00

W 10-06-15